This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.


As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.








291 ENCODER 18 19, 20 ROTOR MOTOR MOTOR DRIVER MOTOR-DRIVING INTERFACE 261 DETECTION INTERFACE BUS INSTRUCTION GENERATOR MICRO COMPUTER **PROCESSOR** MICRO RAM ROM 21b+ 21a+



292 ENCODER
18 30, 31, 39 ROTOR 37, 38 MOTOR 25 MOTOR DRIVER MOTOR-DRIVING 262 INTERFACE DETECTION INTERFACE BUS **NSTRUCTION** MICRO COMPUTER **PROCESSOR** GENERATOR MICRO RAM ROM 21a+ 21b+ 21c+

OBLON, SPIVAK, et al Docket No: 246091US2 Inventor: Toshiyuki ANDOH, et al. Serial No: 10/725,450 Replacement Sheet









FIG. 8








OBLON, SPIVAK, et al Docket No: 246091US2

Inventor: Toshiyuki ANDOH, et al.

FIG. 11








FIG. 12


Replacement Sheet


FIG. 13











OBLON, SPIVAK, et al Docket No: 246091US2 Inventor: Toshiyuki ANDOH, et al.

FIG. 17




FIG. 18




FIG. 19






FIG. 20



OBLON, SPIVAK, et al Docket No: 246091US2 Inventor: Toshiyuki ANDOH, et al.

FIG. 21



Replacement Sheet

FIG. 22

